

Bühler Services
Partnering for better outcomes

Optimize your
sorter's performance.



After approximately 2 billion cycles on small dry products and 0.8 billion cycles on wet and frozen products, your sorter will begin to reject a higher proportion of good products, resulting in a lower accept rate and subsequently a lower quality product.

At this point it is advisable to have the ejector refurbished and bring it back to their original performance. This process can be carried out at our state-of-the-art in-house refurbishment area. Additionally, we replace all wearable parts, making them as good as new. The ejector refurbishment process will see minimal downtime for you – that's our promise.

This is the most efficient option, at a fraction of the cost of a new ejector. By refurbishing the ejectors under our TotalCare offering, you will enjoy greater cost savings and enhanced performance. You will also be practicing sustainability thanks to a reduction in product waste and a minimized carbon footprint.



A part of the TotalCare service package



Bühler UK Ltd
20 Atlantis Avenue
London, E16 2BF, United Kingdom
sortersales@buhlergroup.com

T +44 (0)20 7055 7777
www.buhlergroup.com

BÜHLER